

COATING	SURFACE					METHOD		
	Alumi- nium	Steel Acier	Stainless Steel Inox	Copper & alloys Cuivre Cuivreux	Titanium Titane	Piece Pièce	Frame Cadre	Barrel Tonneau
Chromic anodizing (undyed or dyed) <i>Oxydation anodique chromique (incolore, colorée, bichro)</i>	■					■	■	
Sulphuric anodizing (undyed or dyed) <i>Oxydation anodique sulfurique (incolore, coloré, bichro)</i>	■				■	■	■	
Hard anodizing (undyed or dyed) <i>Oxydation anodique dure (incolore, coloré, bichro)</i>	■					■		
Thin film anodizing (undyed) <i>Oxydation anodique faible couche Incolore</i>	■					■	■	
Chromatation (Alodine 1200, Surtec 650, TCS/PACS)	■					■	■	
Passivating Passivation			■			■	■	■
Chemical conversion of titanium <i>Conversion titane</i>					■	■	■	
Cadmium plating (CrIII, CrVI) <i>Cadmiage (sans ou avec passivation CrIII/CrVI)</i>	■	■	■	■		■	■	■
Tin plating Etamage	■	■	■	■		■	■	■
Medium phosphor chemical Nickel plating <i>Nickelage chimique moyen phosphore</i>	■	■	■	■		■	■	■
Zinc plating (CrIII, CrVI or dyed) <i>Zingage (CrIII, CrVI, coloré)</i>	■	■	■	■		■	■	■ (*)
Zinc-Nickel plating (CrIII) Zinc Nickel (CrIII)	■	■	■	■		■	■	
Degassing Dégazage		■						
Micro or Sandblasting <i>Microbillage ou Sablage</i>	■	■	■					
Ultrasonic degreasing <i>Dégraissage par ultrasons</i>	■	■			■			
Non destructive testing (eddy currents, fluorescence,...) Contrôles non destructifs (courants de foucault, fluorescence, ...) Destructive testing (salt spray tests, ...) Contrôles destructifs (brouillards salins, ...) Masking Epargne								

(*) Black color not concerned